

मालेगांव महानगरपालिका, मालेगांव

🖺 (02554) 231805, (Ex.216) फॅक्स 230814 आरोग्य विभाग



जा.क्र.मामनपा/आरोग्य विभाग/ १२९० /२०२४

दिनांक :- २६/०३/२०२४

CERTIFICATE OF HEALTH & HYGIENIC CONDITION OF THE SCHOOL "TO WHOM IT MAY CONCERN"

This is to certify that the premises of VIDYA VIKAS INTERNATIONAL SCHOOL, Gat NO. 248 near Jai Bajrang Oil Mill, Bhaygaon, Malegaon has been inspected by our officers. It has been found that the school has mentioned very clean, healthy and hygienic atmosphere.

Dr. Jayashri Avinash Aher

Health officer

Malegaon Municipal Corporation



PAN: AALCC4348R

Food Testing Laboratory | Water and Environmental Testing | Civil Engineering Material Testing | Highway Tests | Soil Investigation | Non Destructive Test | Structural Audit | PMC | Survey |

SR. NO.	TEST	UNIT	RESULTS	ACCEPTABLE LIMITS AS PER IS10500:2018	TEST METHOD
08	Total Alkalinity as CaCO3	mg/lit.	44.16	<200.00	АРНА 23 rd Ed 2017, 2320 В
09	Chlorides as Cl	mg/lit.	7.83	<250.00	IS 3025:2019 Part 32
10	Sulphate as SO4	mg/lit.	3.19	<200.00	IS 3025:2019 Part 24
11	-Nitrate as NO3-H	mg/lit.	0.23	<45.00	IS 3025:2019 Part 34
12	Fluoride as F	mg/lit.	0.021	<1.00	APHA 23 rd Ed 2017, 4500-F ⁻ D
13	Calcium as Ca	mg/lit.	9.52	<75.00	APHA 23 rd Ed 2017, 3500 Ca
14	Magnesium as Mg	mg/lit.	2.89	<30.00	APHA 23 rd Ed 2017, 3500 Mg
15	lron	mg/lit.	0.058	<0.3	APHA 23rd Ed 2017 3500 Fe B

REMARKS: As per results obtained are complying with IS 10500:2018 therefore above water sample is chemically potable.

Note:-This report is generated against the sample submitted to the lab.

For Civil Tech India Pvt Ltd.

Head Chemist
Vitthal Nerkar



Report No :CT/NSK/R/03670/24

2 of 2



PAN: AALCC4348R

Food Testing Laboratory | Water and Environmental Testing | Civil Engineering Material Testing | Highway Tests | Soil Investigation | Non Destructive Test | Structural Audit | PMC | Survey |

Report No:-CT/NSK/R/03670/24 ULR No.:-TC536424000001489F

Date:-29/03/2024

TEST REPORT

Client Name

:- Vidya Vikas International School

Address

:- 248, Nilgavan-Kashti Road, Bhaygaon, Tal-Malegaon, Dist-Nashik 423203

Maharashtra

Sample Description

:- RO Water

Sample Quantity/Packaging :- 2 lit. plastic Bottle

Sample Mark

:- Drinking Water

Job No.

:- 032802

Date of receipt of material. :- 28-03-2024

Date of performance of test

:-28-03-2024

SR. NO.	TEST	UNIT	RESULTS	ACCEPTABLE LIMITS AS PER IS10500:2018	TEST METHOD
01	Colour	Hazen	0.2	0.3	IS 3025:2018 Part 4
02	Odour		Agreeable	Agreeable	IS 3025:2018 Part 5
03	Turbidity	NTU	0.3	<1.00	IS 3025:2017 Part 10
04	Taste		Agreeable	Agreeable	IS 3025:2017 Part 7
05	Total Dissolved Solids	mg/lit.	72	<500.00	IS 3025:2017 Part 16
06	рН	y 	7.20	6.5-8.5	IS 3025:2017 Part 11
07	Total Hardness as CaCO3	mg/lit.	35.64	<200.00	IS 3025:2017 Part 21



Report No :CT/NSK/R/03670/24



PAN: AALCC4348R

Food Testing Laboratory | Water and Environmental Testing | Civil Engineering Material Testing | Highway Tests | Soil Investigation | Non Destructive Test | Structural Audit | PMC | Survey |

Report No:-CT/NSK/R/03671/24

Date :-29/03/2024

TEST REPORT

Client Name

:- Vidya Vikas International School

Address

:- 248,Nilgavan-Kashti Road, Bhaygaon, Tal-Malegaon,Dist-Nashik

423203, Maharashtra

Sample Description

:- RO Water

Sample Quantity/Packaging :- 250 ml Sterilized Water

Sample Mark

:- Drinking Water

Job No.

:- 032802

Date of receipt of material.

:- 28-03-2024

Date of performance of test :-28-03-2024

SR. NO.	TEST	UNIT	RESULTS	ACCEPTABLE LIMITS AS PER IS10500:2018	TEST METHOD
01	Total Coliform	/100 ml	Absent	Absent	IS 15185:2016
02	Escherichia Coli	/100 ml	Absent	Absent	IS 15185:2016

Remark: As per results obtained are complying with IS 10500:2018, above water sample is bacteriolgically potable.

Note:-This report is generated against the sample submitted to the lab.

For Civil Tech India Pvt Ltd.

Head Chemist

Vitthal Nerkar

Report No :CT/NSK/R/03671/24

1 of 1